

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

	Day	рН	Alk	Phos	Other	Y/N
	1					
	2					
	3					
	4					
	5	7,5				V
	6					•
	7	1				
	8					
	9					
	10	7.4				Y
	11					-
	12					
*	13					
	14					
	15					
	16					
	17	7.6				V
	18					
	19					
	20	,				
	21	,				
	22					$\neg$
	23					
	24	2,5				V
	25					_
	26					
	27					
	28					
	29					
	30					
	31	7.6				
(N	0 = N	= Exc	ursion)	Total	N's	3

< <have been="" for<="" met="" minimums="" th=""><th colspan="4">County: Josephine Agency: JOSEPHINE COUNTY  ENTRY POINT</th></have>	County: Josephine Agency: JOSEPHINE COUNTY  ENTRY POINT					
this day?	EP-A					
PWS ID 4194765						
BECKLIN HOLDINGS INC						
Sample pe	riod: <u>Tuly /2023</u> Month/Year					

Number of excursions during this month: \_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by State:	
pH 7.3	
Print Name: William LA BARGE	
Signature: William La Box	
Date & Phone#: 7/31/23 541-476-8871	
Send to DWP within 10 days after end of sampling period	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Reference