

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	AIN	F1105	Other	Y/N	< <have< th=""><th>County: Josephine Agency: JOSEPHINE COUNTY</th></have<>	County: Josephine Agency: JOSEPHINE COUNTY	
1						minimums		
2						been met for	ENTRY POINT	
3						this day?	EP-A	
4							PWS ID 4194765	
5						BECKLIN HOLDINGS INC		
6								
7	7,5				V	Sample period: <u>August / 2023</u> Month/Year		
8								
9							Worth Four	
10						Number of excursions during this month:		
11						(Over 9 excursions in 6 months is a violation.		
12 13						Entry Point and Distribution excursions are		
14	7 8				\	cumulative). A	An 'excursion' is any day in which the	
15	1,6				Y	water quality parameter(s) fall below the minimum set by the State.		
16						set by the Stat	e.	
17		Water the state of						
18						Refere	nce	
19					-			
20					-		linimum Water Quality	
21	7,6				V		arameter(s) as set by State:	
22	710						pH 7.3	
23								
24								
25								
26								
27						Drint No.	ma: //// / n	
28	7.5				Y	Print Name: William La Barge Signature: W. Man La Page		
29							Chanatte aland	
30							7 7 7 7 001	
31						Send to I sampling	DWP within 10 days after end of	
	I = Evo	ursion	Total	NI - F	0	Samping	penou	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/