

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th></th><th>County: Lane</th><th>Agency: LANE COUNTY</th></have<>		County: Lane	Agency: LANE COUNTY	
1	7.41					minimu		ENTRY	POINT	
2						been m				
3						this day	?	EP		
4								PWS ID 4	195379	
5							EMER	RALD CHRIST	ΓIAN ACADEMY	
6										
7						Sa	mple pe	riod: <u>12/2</u>	021	
8						Month/Year				
9	· .								2	
10						Number of excursions during this month:				
11				and the same of th						
12		4000, L.				Entry Point and Distribution excursions are				
13						cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.				
14	1									
15	7.36					Sel Dy	liie Stat	. G.		
16										
17						Reference				
18										
19								linimum Wate		
20						*	Р	arameter(s) a	as set by State:	
21								pH 7.2		
22										
23										
24										
25						7:				
26								. 12/13/	12/11/1	
27								me:William	Centrella	
28	7 10							re: Wille	Certilla	
29 30	7.28					l	Date & F	Phone#: <u>//3</u> /	2079	
31				8		9	Send to	DWP within 10	0 days after end of	
			\= 1		A	1	sampling	g period		
10 = N	v = ⊨xc	cursior) Tota	I N'S	0					

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/