

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th></th><th>County: Lane</th><th>Agency: LANE COUNTY</th></have<>		County: Lane	Agency: LANE COUNTY
1						minimu		ENTRY	
2						been m		ENTRI	POINT
3						this day	/?	EP	-A
4								PWS ID 4	195379
5						EMERALD CHRISTIAN ACADEMY			
6	7,5								
7						0-		Made Ag	20mbro /2024
8						Sa	ımpıe pe	erioa:	ember / 2024
9									Ontilly Teal
10						Numb	er of ex	cursions dur	ing this month: _ 💍
11						(Over	9 excurs	sions in 6 mon	ths is a violation.
12				,					excursions are
13	7.4					cumu	lative). A	An 'excursion' i	is any day in which the
14								, ,	all below the minimum
15	-					set by	the Stat	te.	
16									
17							Refere	nce	W F
18									2
19								linimum Wate	
20							Р	arameter(s) a	s set by State:
21								pH 7.2	
22	147								
23	1.4								
24							9		
25 26									
27								11.11	0 1.1/
28						*	Print Na	me/ <u>///////////////////////////////////</u>	Centrella
29							Signatuı	re: Willia 10	ubille.
30	7,5						Date & F	Phone#: <u>/2/3</u>	0 (2024 541)-746-1708
31	(1)						Send to	DWP within 10	days after end of
	l – Eva	urcion	\T4-				sampling	g period	3
140 - 1	V = Exc	ursion) i ota	I M.S	0				

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/