

System Name TU-TU-TUN LODGE / FOUR SEASONS RESORT

PWS ID# 4 1 91199

Month/Year MAR-2024

Entry Point: EP-A

Required Minimum Residual **1.50 mg/L**


Date	Time	Source(s) in use	Lowest free chlorine residual at entry point to distribution system (mg/L)	Notes
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19		SRC AB-WELL L122738	1.88	
20		SRC AB-WELL L122738	1.68	
21		SRC AB-WELL L122738	1.58	
22		SRC AB-WELL L122738	1.63	
23		SRC AB-WELL L122738	1.77	
24		SRC AB-WELL L122738	1.89	
25	9am	SRC AB-WELL L122738	1.81	off boil water
26	10am	SRC AB-WELL L122738	1.72	
27	10am	SRC AB-WELL L122738	1.75	
28	11am	SRC AB-WELL L122738	1.81	
29	10am	SRC AB-WELL L122738	1.86	
30	10am	SRC AB-WELL L122738	1.71	
31	10am	SRC AB-WELL L122738	1.61	

Was the chlorine residual ever less than the required minimum residual of mg/L?  No  
 If yes, what was the longest time period until the required level was restored? hours – if > 4 hours, Drinking Water Program to be notified by end of next business day.

**GWS Serving 3,300 or Fewer**  
 If yes, did you monitor every four hours until the residual returned to mg/L as required?  Yes  
 No  
 Attach those results and submit them with this form.

**GWS Serving More Than 3,300**  
 Did continuous monitoring equipment fail at any time this reporting month?  Yes  No  
 If yes, were grab samples collected every four hours until the continuous monitoring equipment was returned to service as required?  Yes  No  
 Attach grab sample results and submit them with this form.

Date continuous monitoring equipment failed:  
 / /  
 Date it was returned to service:  
 / /

Printed Name: Marcus Dean Harshman  
 Signature:   
 Date: 04/01/2024

Title: Maintenance Manager  
 Phone #: (541-698-8318)

TuTuTun Lodge / Four Seasons Resort  
 PWSID 41 91199