


State of Oregon Drinking Water Section  
**Monthly UV Disinfection Report for Ground Water Systems Requiring 4-log Viral Inactivation**

System Name Salmon Run Golf Course

PWS ID# 41 95127

Month/Year Feb/2026 Entry Point: A

Required Minimum Dose 186 mJ/cm<sup>2</sup> 

Date	Time	Source(s) in use	Any UV Alarms? (Y/N)	Notes
1		Well, SRC-AA		
2		Well, SRC-AA		
3	0748	Well, SRC-AA	N	Calibrated
4		Well, SRC-AA		
5		Well, SRC-AA		
6		Well, SRC-AA		
7		Well, SRC-AA		
8		Well, SRC-AA		
9	0839	Well, SRC-AA	N	
10		Well, SRC-AA		
11		Well, SRC-AA		
12		Well, SRC-AA		
13		Well, SRC-AA		
14		Well, SRC-AA		
15		Well, SRC-AA		
16		Well, SRC-AA		
17	1327	Well, SRC-AA	N	
18		Well, SRC-AA		
19		Well, SRC-AA		
20		Well, SRC-AA		
21		Well, SRC-AA		
22		Well, SRC-AA		
23		Well, SRC-AA		
24	1009	Well, SRC-AA	N	
25		Well, SRC-AA		
26		Well, SRC-AA		
27		Well, SRC-AA		
28		Well, SRC-AA		

Was the minimum UV dose ever less than the required dose of 186 mJ/cm<sup>2</sup>? Or was the alarm ever triggered?  Yes  No  
 If yes, was a boil notice issued, and DWS contacted? If not, please explain:

**This form is for groundwater systems where no residual disinfection has been required to prevent regrowth of pathogens in the pipes.**

Date & time UV reactor failed:  am  pm  
 Date & time it was returned to service:  am  pm

Printed Name: Brenda L Vasquez Title: DRC  
 Signature: Brenda L Vasquez Phone #: (541) 254-1909  
 Date: 03/06/2026

Operator Certification #: T2-D1 070226  
 OR  
 Small Groundwater System