

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН		Phos		Y/N
1	Plo	int	do	NΛ	
2	ì		F	77	
2 3 4 5 6				DOUT	(V)
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30	1	1			
31					
lo = N = Excursion) Total N's					

<<Have minimums been met for this day?

County: Clackamas Agency: REGION 1 ENTRY POINT

EP-A

PWS ID 4100187

CLACKAMAS RIVER WATER -CLACKAMAS

Sample period:

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

-Reference							
Minimum Water Quality Parameter(s) as set by State:							
рН	7.5						
Alk	16.5	(Alkalinity)					

Print Name: Trac Signature:

Date & Phone#: 5-

Send to DWP within 10 days after end of sampling period