Water Quality Parameter Monitoring Form

1

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""></have<>
1	7.56				7	minimums been met for this day? PWS ID: 41 System Name: Hego Joint Warter & Senitarry Entry Point: A Sample Period: APIII 2024 Month/Year Number of excursions* during this month: (Count the number of days when any WQP was less than the minimum required) Total excursions during the previous 5 months: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative) For OHA use only Minimum Water Quality Parameters as set by pH 7.2 Alk (Alkalinity) PO4 (Orthophosphate) Other Print Name: 4000 Chitwood Signature: 2000
2	7.54				11	
3	7.53			7 .		
4	7.5			A		
5	7.54			. /	1	
6	7.48					
7	7.52					
8	7.53					
9	7.5					
10	7.48					
11	7.5%					
12	7.92	and the second second				
13	7.85					
14	7.83					
15	7.8		482			
16	7.76					
17	7.73					
18	7.7					
19	7,51					
20	7.58					
21	7.61		14.			
22	7.66					
23	7.54					
24	7,63					
25	7.53					
26	2.44					
27	7,45					
28	7,5					
29	7,58					
30	7.44					
31						Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/