

## 2020 Cross Connection Annual Summary Report (ASR)

Water System Name and PWS ID# BEAVERTON, CITY OF, 41-00081

System Size Large System, 300+ connections

**Date Report was Received** 03/19/21 11:16 AM

ASR Contact Ben Henderson

Email Address bhenderson@beavertonoregon.gov

**Contact Phone Number** 503-572-0491

**Residential Connection 23.303.00** 

High Hazard Connection 1147

Other Connections 22,156.00

**Total Connections** 46606

**Enabling Authority** Yes

Did you revise your Enabling Authority? No

## This section for LARGE Systems Only

Cross Connection Specialist Ben Henderson

Specialist Cert  $\#^{6525}$ 

WS Employee/Contracted Water System Employee, or

Phone # 503-572-0491

Email Address bhenderson@beavertonoregon.gov

## Written Backflow Protection Program

Written BFP program plan? Yes

List of high hazards Yes

Procedure Yes

Notify Water Users Yes

Type of Protection Yes

Corrective Action Yes

Current Records Yes

Public Education Yes



## 2020 Cross Connection Annual Summary Report (ASR)

Do you have any RPs? Yes

How many 1147

Tested 1147

Passed 1147

Failed 0

% of RPs tested 100%

Comments

Do you have any DCs? Yes

How many 8117

Tested 8116

Passed 8107

Failed 9

% of DCs tested 100%

Comments The one double check not tested was located inside of a residential house where the resident was/is very concerned about letting people into the house with the COVID pandemic going on.

She sart pictures of both shut off handles in the off position-I know this is not the same as a test but due to the pandemic I didn't push further for a test to occur. Of the 9 DC that failed in

Tested 104
Passed 104
Failed 0
% of PVBs Tested 100%

How many 104

Comments

I certify the information provided is true to the best of my knowledge. Providing false information may result in penalties to the individual and to the water system