

Water System Name and PWS ID# ORCHARD HEIGHTS WATER ASSN, 41-00783 System Size Small System, 1-299 connections
Date Report was Received 03/08/21 10:34 AM ASR Contact Doug Priest Email Address dpriest@cityofsalem.net Contact Phone Number 503-428-8703
Residential Connection 156 High Hazard Connection 0 Other Connections 1 Total Connections 157
Enabling Authority Yes Did you revise your Enabling Authority? No
This section for LARGE Systems Only
Cross Connection Specialist Specialist Cert # WS Employee/Contracted Phone # Email Address Written Backflow Protection Program Written BFP program plan? List of high hazards Procedure Notify Water Users Type of Protection Corrective Action Current Records Public Education

<p>Do you have any RPs? Yes</p> <p>How many 1</p> <p>Tested 1</p> <p>Passed 1</p> <p>Failed 0</p> <p>% of RPs tested 100%</p> <p>Comments It is unknown why this service connection has an RP device. The warter service feeds a bathroom and a power sub-station.</p>
<p>Do you have any DCs? Yes</p> <p>How many 156</p> <p>Tested 154</p> <p>Passed 152</p> <p>Failed 2</p> <p>% of DCs tested 99%</p> <p>Comments Two devices failed the initial test and are in need of repair. We are following up with the customer for repairs and the tester to retest the device after repair.</p>
<p>Do you have any PVBs? No</p> <p>How many 0</p> <p>Tested</p> <p>Passed</p> <p>Failed</p> <p>% of PVBs Tested</p> <p>Comments</p>

There were two devices that were unlocatable or inaccessible. One has been located and we are requesting a test from our tester. The other one still needs located and tested, we will work with the customer to find the device and get the assembly tested.

I certify the information provided is true to the best of my knowledge. Providing false information may result in penalties to the individual and to the water system