

11/5/2025

HOWARD ROBBINS
VILLADOM MOBILE HOME PARK
1312 MASTERSON LN
LAFAYETTE, CA 94549-2619

RE:Installation of treatment to maintain a disinfectant residual due to persistent coliform bacteria at OR4100525

Dear HOWARD ROBBINS,

Due to recent coliform sample results, the Oregon Health Authority, Drinking Water Services (DWS) is requiring another coliform investigation. The number of coliform investigations at your water system without removing the source of the coliform bacteria requires the installation of treatment to maintain a disinfectant residual throughout the distribution system according to Oregon Administrative Rule 333-061-0032(6)(g).

Treatment must be installed no later than 5/1/2026. Plan review is required prior to installation. Please review the requirements at www.healthoregon.org/pwsplanreview.

If you have any questions please contact Bill Goss/Amy Word at (541) 276-8006.

Respectfully,

Drinking Water Services

cc: Bill Goss/Amy Word, DWS