
Public Health Division

Drinking Water Services

Tina Kotek, Governor

October 31, 2024

Seyed Ahmad Elk Flat Water Company 6505 Elk Flat Road Arch Cape, OR 97102



Dear Seyed Ahmad,

Recent samples reported for your water system indicate coliform bacteria in the drinking water caused a violation of the maximum contaminant level (MCL) for *E. coli* bacteria. The presence of these bacteria indicates that the water may be contaminated with human or animal wastes. Human pathogens in these wastes can cause short-term effects, such as diarrhea, cramps, nausea, headaches, or other symptoms. They may pose a greater health risk for infants, young children, the elderly, and people with severely compromised immune systems. OAR 333-061-0097

Please continue consultation with Nicole Alfafara of the Oregon Health Authority, Drinking Water Services at 503-278-1531 so that you can disinfect the water system and abate the contamination completely, as quickly as possible.

You can contact DWS circuit rider for technical assistance at mgochnour@civilwest.net or 541-266-8601. Visit the webpage: https://www.oregon.gov/oha/PH/HEALTHYENVIRONMENTS/DRINKINGWATER/OPERATIONS/Pages/circuitrider.aspx for more information about the DWS circuit rider program.

Elk Flat Water Company

Page 2

The actions described in this letter are required by Oregon Administrative Rule 333-061-0100. Please contact me at bradley.k.daniels@oha.oregon.gov or (503) 735-5438 if you have any questions or to discuss the actions required in this letter.

Thank you for your immediate attention to this matter.

Respectfully,

Brad K. Daniels

Compliance Specialist

Oregon Health Authority, Drinking Water Services

cc: Nicole Alfafara, Oregon Health Authority, Drinking Water Services