

Health Authority

800 SE Emigrant Ave., Suite 240 Pendleton, OR 97801 (541) 276-8006 FAX (541) 276-4778 www.healthoregon.org/dwp

August 12, 2016

Douglas Mallory Troy Resort, PWS ID #4193931 84570 Bartlett Road Enterprise, Oregon 97828

Re: Corrective action required due to E. coli contamination in a groundwater source

Dear Mr. Mallory,

On October 6, 2015 sample results were reported to the Oregon Health Authority, Drinking Water Services (DWS) confirming well #2 serving the Troy Resort water system, identified by well log# WALL 4, is contaminated by *E. coli* bacteria. You were therefore required to take corrective action to protect water users against exposure to the bacteria according to Oregon Administrative Rule 333-061-0032(6). You have not notified DWS that corrective action was completed as required.

You must submit construction plans for 4-log viral disinfection treatment of the water, or plans for another method of consistently eliminating *E. coli* bacteria from finished drinking water at the Troy Resort water system, no later than **October 1, 2016**. Information on plan review requirements including the \$248 fee is available online at www.healthoregon.org/pwsplanreview. You must also complete the proposed construction or corrective action no later than **December 31, 2016**. The boil/do not drink notices must remain posted until the treatment system is installed and final approval is granted. See my March 17, 2016 letter for more details.

If you have any questions please contact me at 541-966-0900 or by email at william.h.goss@state.or.us

Respectfully,

William Goss, P.E.

Regional Engineer

cc: Brad Daniels, Oregon Health Authority, Drinking Water Services Mark Hemstreet, c/o Shilo Inns, Portland, OR Laina Fisher, RN, Wallowa County Health Department