

7/28/2025

KEVIN JONES
UNITED PARCEL SERVICE
4455 7TH AVE S
SEATTLE, WA 98108

RE:Installation of treatment to maintain a disinfectant residual due to persistent coliform bacteria at OR4194874

Dear KEVIN JONES,

Due to recent coliform sample results, the Oregon Health Authority, Drinking Water Services (DWS) is requiring another coliform investigation. The number of coliform investigations at your water system without removing the source of the coliform bacteria requires the installation of treatment to maintain a disinfectant residual throughout the distribution system according to Oregon Administrative Rule 333-061-0032(6)(g).

Treatment must be installed no later than 1/29/2026. Plan review is required prior to installation. Please review the requirements at www.healthoregon.org/pwsplanreview.

If you have any questions please contact Stephen Kirkley/Rebecca Duerr/Nate Tisdell/Shane Sanderson/Alyson Reynolds at (541) 967-3821.

Respectfully,

Drinking Water Services

cc: Nick Alviani, DWS

Stephen Kirkley/Rebecca Duerr/Nate Tisdell/Shane Sanderson/Alyson Reynolds,
Linn County