

August 19, 2015

Ed Murdock
Wild Rivers Golf Management, LLC
96418 Oceanside Drive East
Brookings, OR 97415

RE: Notice of Non-Compliance Regarding the Salmon Run Golf Course Public Water System

Our records indicate that Wild Rivers Golf Management, LLC (Management) owns and operates the Salmon Run Golf Course (Salmon) water system located at 99040 S Bank Chetco River Rd. in Brookings, Oregon. Therefore, Management is a water supplier as defined in Oregon Revised Statute (ORS) 448.115(12) and Oregon Administrative Rule (OAR) 333-061-0020(207) and has specific responsibilities as defined in OAR 333-061-0025.

The Salmon water system is a transient non-community public water system identified by public water system ID OR41-95127, serves approximately 100 people, and is subject to regulation according to ORS 448.115 to 448.290 and OAR 333-061-0005 to 333-061-0272.

The Oregon Health Authority, Public Health Division, Center for Health Protection, Drinking Water Services (DWS) has reviewed the operation of the Salmon water system. This review has found that Management is not in compliance with the following Oregon Administrative Rules, and is therefore not meeting its responsibilities as a water supplier as prescribed by the Oregon Drinking Water Quality Act (ORS 448.115 to ORS 448.290) and rules.

DESCRIPTION OF RULE VIOLATIONS

- Violation No. 1: OAR 333-061-0036(6)(w)(C)(i) requires that additional source water sampling must be collected from a groundwater source where a hydrological assessment has determined the source to be highly sensitive due to aquifer characteristics. Scott Curry sent you a letter on March 16, 2015 informing you that monthly assessment sampling for SRC-AA (Well) for one year would be required

starting April 2015. As of this notice, DWS has received one assessment sample collected April 22, 2015, which is a violation of the rule if, in fact, no other samples were collected.

- Violation No. 2: OAR 333-061-0036(2)(d), in part, requires water suppliers to conduct sampling for nitrate at public water systems. However, Management did not report nitrate sample results for the Salmon water system for the 2013 and 2014 yearly monitoring periods, which constitutes two violations of OAR 333-061-0036(2) if samples were, in fact, not collected.

ACTIONS REQUIRED TO ACHIEVE COMPLIANCE

Due to the rule violations identified above, Management is required to complete the following actions relating to the Salmon water system:

- Compliance Action No. 1: Management must collect source water samples as prescribed in OAR 333-061-0036(6)(w)(C)(ii). Sample results must be reported to DWS by the 10th of the month following the collection date.
- Compliance Action No. 2: Compliance Action No. 1: Management is required to monitor for nitrate according to OAR 333-061-0036(2)(d) and report the sample results to DWS no later than October 10, 2015.

If you do not comply with the deadlines specified in this letter, the continued non-compliance may result in additional enforcement action including the assessment of civil penalties as prescribed by OAR 333-061-0090. Please contact Scott Curry at (541) 618-7872 to discuss the compliance actions specified in this letter.

Respectfully,



Janet Brock
Compliance Specialist
Oregon Health Authority, Drinking Water Services

cc: Scott Curry, Oregon Health Authority, Drinking Water Services
Brody Hodges, Curry County Environmental Health