

'No = N = Excursion) Total N's

Water Quality Parameter Monitoring Form

HECEIVEL

Lead & Copper Rule Corrosion Control Water Services

Day	рН	Alk	Phos	Other Y/			
1	7.2				minimums been met for this day? PWS ID: 41		
2							
3							
4					System Name: Periwin Kla Mobile Estate		
5			·		Sample Period: July 3034 Month rear		
6							
7	7.4						
8					Number of excursions* during this month:		
9					(Count the number of days when any WQP was less than the minimum required) Total excursions during the previous 5 months. (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative) For OHA use only Minimum Water Quality Parameters as set by pH 7, Z Alk (Alkalinity) PO4 (Orthophosphate) Other		
10				1 34			
11							
12			243				
13	7.4						
14							
15							
16			-				
17	7.3						
18							
19							
20							
21	- 11		· ·				
22	7.4		-=				
23							
24	- 1						
25	7.2						
			-				
27			-		Print Name: Steg Attrell.		
28 29	70				Signature: As Attell		
30	7.3		-		Send to DWP within 10 days after end of		
31				5			

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period