

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th></th></have<>		
1	7.36				YES	minimums		
2	7.78				YES	been met	ENTRY POINT	
3	7.46				YES	for this day?	Α	
4	7.34				YES		PWS ID: 4100152	
5	7.40				YES		BROWNSVILLE, CITY OF	
6	7.97				YES			
7	7.65				YES	Sample	e Period: Mar-21	
8	7.44				YES		Month/Year	
9	7.58				YES			
10	7.53				YES	Number of excursions* during this month:		
11	7.41				YES	(Count the number of days when any WQP was less		
12	7.41				YES	than the minimum required)		
13	7.28				YES			
14	7.29				YES			
15	7.41				YES			
16	7.45				YES	(Over 9 excursions in 6 months is a violation. Entry		
17	7.47			1	YES	-l VEC		
18	7.45				YES	Is the sy	stem in compliance? YES	
19	7.36				YES			
20	7.52				YES	Reference		
21	7.42				YES			
22	7.28				YES		Minimum Water Quality	
23	7.63				YES	P	arameters as set by State:	
24	7.27				YES			
25	7.44			1000	YES		pH 7.2	
26	7.20				YES	6		
27	7.62	2			YES	5		
28	7.31				YES			
29	7.35	5			YES	Print Name: Karl Frink		
30	8.23	3			YES			
31	7.91	1			YE			
(No	= N = E	xcursi	on) 1	Total N	s 0	Send to 0	OHD within 10 days after end of sampling period.	

= N = Excursion) Total N's Send to OHD within 10 days after end of sampling period.

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381