

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other Y/N	THE RESIDENCE OF THE PARTY OF T
1	1		1)1 4	minimums ENTRY POINT
2	M	1te	1	144	been met for this day? PWS ID: 41 0 0 1 7 /
3		T	- -	,	inamentation to the continue of the continue o
4	\underline{U}			196	System Name: Loulton City of
5					Entry Point: 21511 NW Panthe Co. Rd
6					Sample Period: Tune 2022
7					Month/Year
8					Number of excursions* during this month:
9					(Count the number of days when any WOP was
10					less than the minimum required)
11					
12					Total excursions during the previous 5 months:
13					(Over 9 excursions in 6 months is a violation Entry
14			automotiva para para para para para para para pa		Point and Distribution excursions are cumulative)
15					
16	~~~				For OHA use only
17					Minimum Water Quality
18					Parameters as set by
19					photoconstruction of network and network a
20					рН
21					Alk (Alkalinity)
22			1		PO4 (Orthophosphate)
23		1			Other ()
24		1	14		
25			V '		
26			0		7 17
27					Print Name: Sum W Surulaus
28					Signature: P. A. L. Burger
30					Date: 2 - 92
31					
	po l				Send to DWP within 10 days after end of sampling period
(NO = N =	No = N = Excursion) Total N's			N's	annymig belied

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/