

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day 1 2 3 4 5 6 7 8 9	pH Alk	Phos Other Y/N	Key Side of this day? PWS ID: 41 0 0 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
11 12 13 14 15 16			Total excursions during the previous 5 months: o (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative) —For OHA use only
18 19 20 21 22 23			Minimum Water Quality Parameters as set by pH Alk (Alkalinity) PO4 (Orthophosphate) Other ()
24 25 26 27 28 29 30 31		Total N's	Print Name: Buyay W Buvukaun Signature: Byan W- Burulaun Date: 2-6-23 Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/