

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	PO4	Sili	Y/N	<has sample<="" th=""></has>
							met the minimums? DISTRIBUTION
	10/10 1001 W. Gvant 10/10 714 E. Main	800					PWS ID: 41 0 0 1 7 1 System Name:
10		7.8					Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.
	(N = No = Exc		n) To	tal N	s		Minimum Water Quality Parameters as set by State: pH (Alkalinity) Alk (Orthophosphate) Sili (Silicate)
	t Name: <u>Svyau</u> ature: <u>Bya</u>	n U	V. 1. V. 1.	Suv Dur	uha	em	Date:/// 7/22
DHS	Send to (Drinking Water Progra	OHD 1 am, PO	withir D Box	1435 1435	ays a 60, Po	fter e	nd of sampling period d, OR 97293-0350 Phone (503) 731-4381