

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.2	33			У
2 3					
3					
4					
5					
6					
7					
8					
9					
10					
11	7.3	47			Y
12					
13					
14					
15					
16					
17					
18	7.6	38			4
19					
20					
21					
22					
23					
24					
25					
26	7.6	34			Y
27					
28					
29	7.5	35			Y
30					
31					
(No =	No = N = Excursion) Total N's				

< <have< td=""><td colspan="2">County: Hood River Agency: HOOD RIVER COUNTY</td></have<>	County: Hood River Agency: HOOD RIVER COUNTY				
minimums been met for	ENTRY POINT				
this day?	EP-A				
PWS ID 4100172					
CASCADE LOCKS, CITY OF					
Sample period: 4/22 Month/Year					

Number of excursions during this month: _______

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference -					
Minimum Water Quality Parameter(s) as set by State:					
pH Alk	7.0 31.0	(Alkalinity)			

Print Name: Shelden Price
Signature: Shelden Price
Date & Phone#: 541 374 8484

Send to DWP within 10 days after end of

sampling period