

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	/ рН		Α	lk	Phos	Other	Y/N
	1	7.7		22	.0			Υ
	2	7.6		21	. \			Υ
	-3	7.5		20	.9			Υ
	4	7.6		9				Υ
	5	7.6			125-26			Υ
	6	7.6		21.	2			Υ
	7	7.5		21	.			Υ
	8	7.6		21				Υ
	9	7.6		20.	0			Υ
	10	7.6		21.	6			Υ
	11	7.6		0.400				Υ
	12	7.6						Υ
	13	7.6	1	20.	0		20000 304500	Υ
	14	7.6	ľ	20.	6			Υ
	15	7.6	٠.	20.	_			Υ
	16	7.6	-	20.				Υ
-	17	7.6		21.	7			Υ
	18	7.7						Υ
	19	7.7		10.00				Υ
	20	7.7	L					Υ
	21	7.6	'	18.4	+			Υ
L	22	7.7	١	8.5	5			Υ
L	23	7.6	L					Υ
	24	7.6	L					Υ
	25	7.6	L		1			Υ
	26	7.7						Υ
	27	7.7						Υ
_	28	7.6	_	11.2	-			Υ
_	29	7.7	2	0.8	\perp			Υ
	30	7.7	_	٥. لا				Υ
_	31	7.6	2	1.4				Υ
1	N.I	· ·			\ .			1

	20	7.0			Y
	26	7.7			Υ
	27	7.7			Υ
	28	7.6	21.2		Υ
	29	7.7	20.8		Υ
	30	7.7	20.6		Υ
	31	7.6	21.4		Υ
1)	10 = 1	1 = Ex	cursion	Total N's	Ø
		OF	-IΔ Dri	nkina Wata	r Dro

< <have< td=""><td>County: Clackamas Agency: REGION 1</td></have<>	County: Clackamas Agency: REGION 1
minimums	ENTRY POINT
been met for this day?	EP-A
	PWS ID 4100187
CLA	CKAMAS RIVER WATER -
	CLACKAMAS
Sample pe	riod: December 2021
	Month/Year

Number of excursions during this month: \mathscr{S}

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

ter Quality as set by State:

Signature: Traces

Date & Phone#: 01-10-2022 (503) 793-3685

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/