



# Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	7.0	27			Y
2	7.1				Y
3	7.1				Y
4	7.1				Y
5	7.0				Y
6	7.1				Y
7	7.1				Y
8	7.0	42			Y
9	7.0				Y
10	7.0				Y
11	7.1				Y
12	7.0				Y
13	7.0				Y
14	7.1				Y
15	7.0	19			Y
16	7.0				Y
17	7.0				Y
18	7.0				Y
19	7.1				Y
20	7.0				Y
21	7.0				Y
22	7.0	21			Y
23	7.1				Y
24	7.0				Y
25	7.0				Y
26	7.0				Y
27	7.0				Y
28	7.0				Y
29	7.0	23			Y
30	7.0				Y
31	7.0				Y
(No=N=Excursion)Total N's					0

<<Have  
minimums been  
met for this day?

### ENTRY POINT

**PWS ID: 41 00213**

**System Name:** Coquille, City of

**Entry Point:** EP-A

**Sample Period:** Jan-24

**Number of excursions during this month :** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during the previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only

### Minimum Water Quality Parameter as set by State:

pH	<b>7.0</b>	
Alk	<b>16</b>	(Alkalinity)
Phos		(Phos. Max)
Other		( )

**Print Name:**

**Signature:**

**Date:**

Ray Doan  
Ray Doan  
2/2/24

Send to Drinking Water Program within 10 days after end of sampling period.

OHA Drinking Water Program, P.O. Box 14350, Portland, OR 97293-0350

Phone: (971) 673-0405

Website: <http://healthoregon.org/dwp/>