(	DHS							
`	Oregon Department				Water Quality Parameter Monitoring Form			
	of Human Service	es	Lead & Copper Rule Corrosion Control					
Day	pH	Alk	Phos	Sili	Y/N	< <have< td=""><td>County: Lane</td><td>Agency: REGION 2</td></have<>	County: Lane	Agency: REGION 2
1	7.5	N/A	N/A	N/A	YES	minimums		ENTRY POINT
2	7.5	N/A	N/A	N/A	YES	been met for		Entry Point: EP-B
3	7.5	N/A	N/A	N/A	YES	this day?		PWS ID 4100246B
4	7.5	N/A	N/A	N/A	YES		System Name:	Creswell, City of
5	7.5	N/A	N/A	N/A	YES		Sample period:	July-21
6	7.5	N/A	N/A	N/A	YES			Month/year
7	7.6	N/A	N/A	N/A	YES			
8	7.4	N/A	N/A	N/A	YES		Number of excursions during this month:0	
9	7.5	N/A	N/A	N/A	YES		,	in 6 months is a violation.
10	7.5	N/A	N/A	N/A	YES YES			tribution excursions are
11 12	7.5 7.4	N/A N/A	N/A	N/A N/A	YES			cursion' is any day in which the eter(s) fall below the minimun
13	7.4	N/A N/A	N/A N/A	N/A N/A	YES		set by the State.	eter(s) rail below the minimum
14	7.5	N/A	N/A	N/A	YES		Set by the State.	
15	7.4	N/A	N/A	N/A	YES			
16	7.5	N/A	N/A	N/A	YES			
17	7.5	N/A	N/A	N/A	YES		Reference: Minimun	pH set on 11/3/2003 By John Potts.
18	7.4	N/A	N/A	N/A	YES			
19	7.5	N/A	N/A	N/A	YES		Minimum Water Qu	= 1
20	7.4	N/A	N/A	N/A	YES		Parameter(s) as se	et by State:
21 22	7.4 7.9	N/A N/A	N/A N/A	N/A N/A	YES YES		pH 7.1	
23	7.9	N/A	N/A N/A	N/A	YES		Alk N/A	(Alkalinity)
24	7.9	N/A	N/A	N/A	YES		PO4 N/A	(Orthophosphate)
25	7.9	N/A	N/A	N/A	YES		Sili N/A	(Silicate)
26	7.6	N/A	N/A	N/A	YES			
27	7.6	N/A	N/A	N/A	YES		Print Name:	Mike Howard
28	7.6	N/A	N/A	N/A	YES			
29	7.6	N/A	N/A	N/A	YES		Signature: Mik	
30	7.6	N/A	N/A	N/A	YES			541-736-6015
31	7.6	N/A	N/A	N/A	YES			1/2021
o=N=Excursion)			Total N's				thin 10 days after end of sar	1 01
					DHS, Drinking Phone:(971) 6		Box 14350, Portland, OR 97 Website: http://orego	7293-0350 on.gov/DHS/ph/dwp/index.shtml
	İ	1	1 1		1	I	1	