	DHS								
( DHS Oregon Department					Water Quality Parameter Monitoring Form				
of Human Services					Lead & Copper Rule Corrosion Control				
Day	pH	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lane</th><th>Agency: REGION 2</th></have<>	County: Lane	Agency: REGION 2	
1	7.5	N/A	N/A	N/A	YES	minimums	,	ENTRY POINT	
2	8.0	N/A	N/A	N/A	YES	been met for		Entry Point: EP-B	
3	7.8	N/A	N/A	N/A	YES	this day?		PWS ID 4100246B	
4	7.5	N/A	N/A	N/A	YES		System Name:	Creswell, City of	
5	7.5	N/A	N/A	N/A	YES		Sample period:	November-21	
6	7.5	N/A	N/A N/A	N/A N/A	YES	_	Sample period.	Month/year	
7	7.5	N/A	N/A	N/A	YES	_		wonun you	
8	7.8	N/A	N/A	N/A	YES		Number of excursions during this month: _0		
9	7.5	N/A	N/A	N/A	YES		(Over 9 excursions in 6 months is a violation.		
10	7.7	N/A	N/A	N/A	YES			ibution excursions are	
11	7.8	N/A	N/A	N/A	YES		cumulative). An 'excu	ırsion' is any day in which the	
12	7.8	N/A	N/A	N/A	YES		water quality parame	ter(s) fall below the minimun	
13	7.8	N/A	N/A	N/A	YES		set by the State.		
14	7.8	N/A	N/A	N/A	YES				
15	7.5	N/A	N/A	N/A	YES				
16	7.4	N/A	N/A	N/A	YES				
17	7.4	N/A	N/A	N/A	YES		Reference: Minimun	pH set on 11/3/2003 By John Potts.	
18 19	7.5 7.5	N/A N/A	N/A	N/A	YES YES		Mai::::::::::::::::::::::::::::::::::::	-124	
20	7.5	N/A N/A	N/A	N/A	YES		Minimum Water Quality Parameter(s) as set by State:		
21	7.5	N/A N/A	N/A N/A	N/A N/A	YES		Parameter(s) as set	by State.	
22	7.5	N/A	N/A	N/A	YES		pH 7.1		
23	7.5	N/A	N/A	N/A	YES		Alk N/A	(Alkalinity)	
24	7.5	N/A	N/A	N/A	YES		PO4 N/A	(Orthophosphate)	
25	7.5	N/A	N/A	N/A	YES		Sili N/A	(Silicate)	
26	7.4	N/A	N/A	N/A	YES				
27	7.5	N/A	N/A	N/A	YES		Print Name:	Mike Howard	
28	7.5	N/A	N/A	N/A	YES				
29	7.6	N/A	N/A	N/A	YES		Signature: Mike	e Howard	
30	7.5	N/A	N/A	N/A	YES			541-736-6015	
31	x	N/A	N/A	N/A	х		12/2	/2021	
No=N=Excursion) Total N's						Send to DWP within 10 days after end of sampling period			
					DHS, Drinking Phone:(971) 6		Box 14350, Portland, OR 97	7293-0350 n.gov/DHS/ph/dwp/index.shtml	