

**Water Quality Parameter Monitoring Form  
Oregon Health Authority  
Lead & Copper Rule Corrosion Control**

Day	PH	Alk	Phos	Other	Y/N
1	7.2				Y
2	7.1				Y
3	7.2				Y
4	7.2				Y
5	7.1	40.0			Y
6	7.1				Y
7	7.3				Y
8	7.3				Y
9	7.1				Y
10	7.1				Y
11	7.2				Y
12	7.3	40.0			Y
13	7.5				Y
14	7.2				Y
15	7.4				Y
16	7.1				Y
17	7.1				Y
18	7.1				Y
19	7.1	40.0			Y
20	7.1				Y
21	7.1				Y
22	7.4				Y
23	7.1				Y
24	7.1				Y
25	7.1				Y
26	7.4	40.0			Y
27	7.2				Y
28	7.2				Y
29	7.1				Y
30	7.2				Y
31	#N/A				Y
<b>Total N's</b> (No = N = Excursion)					<b>0</b>

<<Have minimums been met for this day?	<b>ENTRY POINT</b>
PWS ID:	4100254
System Name:	City of Depoe Bay
Entry Point:	A
Sample Period:	Jun-24
	<i>Month/Year</i>

**Number of excursions during this month:** 0  
(Count the number of days when any WQP was less than the minimum required)

**Number of excursions during this month:** 0  
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative )

For OHA use only

Minimum Water Quality Parameter(s) as set by State:		
	MIN	
pH	7.1	
Alk	24	(Alkalinity)
PO4		(Orthpphosphate)
Other		(_____)

Print Name: PAUL CARVER

Signature: 

Date: 7-9-24  
Sent to DWP within 10 days after end of sampling period.