

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""></have<>
1						minimums ENTRY POINT
2						been met for this day? PWS ID: 41 0 0 2 9 5
3						uno day:
4	7.0					System Name: Big Spruce MHP
5		\	·			Entry Point: EP-A
6						Sample Period: May 3033
7						Month/Year
8	-					Number of excursions* during this month:
9						(Count the number of days when any WQP was
10						less than the minimum required)
12						Taket assessment and attended to the same
13					-	Total excursions during the previous 5 months:
14						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)
15	1.2					i dina dida dida dida di
16	112				\dashv	For OHA use only
17						
18						Minimum Water Quality Parameters as set by
19						promoterous
20						pH 7.1
21						Alk (Alkalinity)
22						PO4 (Orthophosphate)
23						Other()
24						
25	7.2					
26						
27						Print Name: 1507 14 Vottous on
28						Signature Polled
29						Date: 06-18-6023
30						Send to DWP within 10 days after end of
						sampling period
0 = 1/	= EXCL	irsion)	Total	N'S		

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/