



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	7.25				Y
2					
3	7.40				Y
4					
5					
6	7.35				Y
7					
8					
9	7.25				Y
10					
11					
12	7.30				Y
13					
14					
15					
16	7.20				Y
17					
18					
19	7.35				Y
20					
21					
22	7.1				Y
23					
24					
25	7.2				Y
26					
27	7.1				Y
28					
29	7.1				Y
30					
31					

<<Have minimums been met for this day?

ENTRY POINT

PWS ID: 41

System Name: Big Spruce MHP

Entry Point: EP-A

Sample Period: June 2024
Month/Year

Number of excursions* during this month: ~~15~~ 0
(Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: _____
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only

Minimum Water Quality Parameters as set by

pH

Alk (Alkalinity)

PO4 (Orthophosphate)

Other

Print Name: Jenna Shaughnessy

Signature: _____

Date: 7/3/2024

Send to DWR within 10 days after end of sampling period

(No = N = Excursion) Total N's 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>
Fax - 0694