

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID #	Sample Location	рН	Alk	P04	other	Y/N	<has sample<="" th=""></has>
	#(7.7					met the DISTRIBUTION minimums?
							PWS ID: 41 0 0 2 9 5
	#12	8,5		·		•	System Name: Big Spruce MHP
	4, 10	01-					Sample Period: November 2021 Month/Year
							Sample Frequency: 3 years/ w L&C Sample
	<i>F</i> 27	8.7		•			Distribution Samples required: 1
							Number of excursions during this Sample Period =
							(Number of locations when any WQP was less than the minimum.)
							Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get
							total for sample period.
							For OHA use only
							Minimum Water Quality Parameters as set by
							pH 7.1
							Alk (Alkalinity) PO4 (Orthophosphate)
							Other ()
			• *		8.5		
			-		1		Print Name: Party Latterson
(N = NO = EXCUISION) Otal N'S							Signature: Xatha Date: 12/08/2021

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/