

Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

| ID # | Sample Location | pH | Alk | PO4 | other | Y/N |
|------|-----------------|-----|-----|-----|-------|-----|
| | | | | | | |
| 3 | | 7.8 | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| 15 | | 7.6 | | | | |
| | | | | | | |
| | | | | | | |
| 25 | | 8.1 | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

<Has sample met the minimums? **DISTRIBUTION**

PWS ID: 41 0 0 2 9 5

System Name: Big Spruce MHP

Sample Period: October 2022
Month/Year

Sample Frequency: 3 years/ w L&C Samples

Distribution Samples required: 1

Number of excursions during this Sample Period = _____

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

For OHA use only

Minimum Water Quality Parameters as set by

pH 7.1

Alk _____ (Alkalinity)

PO4 _____ (Orthophosphate)

Other _____ (_____)

Print Name: KATHY JOHNSON

Signature: [Signature]

Date: 11-0-22

(N = No = Excursion) Total N's

Send to Drinking Water Program within 10 days after end of sampling period:
OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>