



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID #	Sample Location	pH	Alk	PO4	other	Y/N
11	Pumphouse / Sp 37	6.55				
13	Pumphouse / Office	7.3				
16	Sp 37	7.2				
18	Office	7.3				
110	Office	7.2				
113	Sp 20	7.2				
115	Office	7.4				
117	Office	7.1				
120	Sp 37	7.1				
122	Sp 20	7.1				
125	Office	7.4				
127	Office	7.1				
129	Sp 20	7.3				
131	↓ Sp 37	7.1				

<Has sample met the minimums? **DISTRIBUTION**

PWS ID: 41 00295

System Name: Big Spruce mtd

Sample Period: July 2024
Month/Year

Sample Frequency: Weekly

Distribution Samples required: _____

Number of excursions during this Sample Period = 1

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

For OHA use only

Minimum Water Quality Parameters as set by

pH 7.1

Alk (Alkalinity)

PO4 (Orthophosphate)

Other

Print Name: Johna Shaughnessy

Signature: _____

Date: 8/2/24

(N = No = Excursion) Total N's

Send to Drinking Water Program within 10 days after end of sampling period:
 OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
 Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>
 Fax 0694