

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""></have<>
1						minimums ENTRY POINT
2						been met for this day? PWS ID: 41 0 0 3 1 1
3	7,5				У	and day:
4						System Name: City of Garibaldi
5						Entry Point: First hydrant before services
6						Sample Period: MAY 12024
7						Month/Year
8						Number of excursions* during this month:
9						(Count the number of days when any WQP was
10						less than the minimum required)
11						
12						Total excursions during the previous 5 months:
13	7.5				Y	(Over 9 excursions in 6 months is a violation. Entry
14						Point and Distribution excursions are cumulative )
15						For OHA use only
16						
17						Minimum Water Quality
18						Parameters as set by
19						pH 7.1
20						Alk (Alkalinity)
21	2 11				<u> </u>	PO4 (Orthophosphate)
	7.4				7	Other ()
23	7 0					
24	7,9				7	
25						<u> </u>
26						
27						Print Name: EVERTON ULIVERA
28 29						Print Name: Everton Universal Signature:
30						Date: 06/05/24
31						Send to DWP within 10 days after end of
	l - F		\ = 4			sampling period
IAO = V	A = EXC	ursion	) Tota	I N'S	0	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/