

# Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.9	44			y
2	7.7	44			y
3	7.9	44			y
4	7.9	48			y
5	7.7	48			y
6	7.7	48			y
7	8	44			y
8	7.7	48			y
9	7.6	44			y
10	7.7	48			y
11	7.7	48			y
12	7.8	52			y
13	7.8	44			y
14	7.7	44			y
15	8.1	48			y
16	7.5	48			y
17	7.9	48			y
18	7.4	48			y
19	7.8	48			y
20	8	48			y
21	8	48			y
22	8	44			y
23	8	48			y
24	7.9	48			y
25	8	52			y
26	8.1	52			y
27	7.9	48			y
28	7.8	48			y
29	7.7	48			y
30	7.8	48			y
31	7.7	48			y

(No= N=Excursion) Total N's **0**

<<Have  
minimums been  
met for this  
day?

**ENTRY POINT**

**EP-A**

**PWS ID 4100323**

**GLENDALE, CITY OF**

Sample Period:

(Month/Year) May 2025

Number of excursions during this month: **0**


(Over 9 excursions in 6 months is a violation. Entry Point and Distribution Excursions are cumulative.)  
An 'Excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

**Minimum Water Quality**

**Parameter(s) as set by State:**

**pH: 7.3**

Print Name: Sean Negherbon

Signature: 

Date: 6/4/25

Send to DWP within 10 days after end of sampling period

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone: (503) 731-4381 Website: [www.ohd.hr.state.or.us/dwp](http://www.ohd.hr.state.or.us/dwp)