

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

| ID# | Sample Location | рН | Alk | PO4 | other | Y/N | <has sample<="" th=""></has> |
|--------------------------------|----------------------|------|-----|-----|-------|--------------|---|
| 1 | 500 SE Butler Rd | 8.25 | | | | | met the DISTRIBUTION minimums? |
| 7 | 700 SE Francis Ave | 8.64 | | | | | PWS ID: 41 00357 System Name: <u>City of Gresham</u> |
| 3 | 4800 SE Welch Rd | 8.70 | | | | | |
| 4 | 1000 SE Larch Ln | 8.67 | | | | | |
| 5 | 1400 NE Hacienda Ct | 8.76 | | | | | Sample Period: <u>January 2024</u> <i>Month/Year</i> |
| 6 | 1200 NE 25th St | 8.78 | | | | | Sample Frequency: Every 6 months Distribution Samples required: 10 |
| 7 | 500 NE Hood Ave | 8.67 | | | | | |
| 8 | 1700 NW 13th St | 8.65 | | | | | |
| 9 | 1500 SW Lillyben Ave | 8.69 | | | | | Number of excursions during this |
| lb | 2600 SW Linneman Dr | 8.45 | | | | | Sample Period = |
| | | | | | | | (Number of locations when any WQP was less than the minimum.) |
| | | | | | | | |
| | | | | | | | Note: Entry Point and Distribution |
| | | | | | | | Excursions are cumulative. Add Entry Point and Distribution Excursions to get |
| | | | | | | | total for sample period. |
| | | | | | . 95 | | |
| | | | | | | | For OHA use only |
| | | | | | | | Main in the Mater Ouglity |
| | | | | | | | Minimum Water Quality Parameters as set by |
| | | | | | | | pH <u>7.5</u> |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | Print Name: Ky Dorokoo |
| (N = No = Excursion) Total N's | | | | | | Signature: W | |
| Date: | | | | | | | |
| | | | | | | | |

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/