



Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	8.00	100			Y
2	7.96				Y
3	8.01	120			Y
4	8.04				Y
5	8.10	120			Y
6	8.00				Y
7	8.24	140			Y
8	8.01				Y
9	7.85	100			Y
10	7.84				Y
11	7.75	80			Y
12	7.91				Y
13	7.70	80			Y
14	7.68				Y
15	7.72	60			Y
16	7.75				Y
17	7.77	80			Y
18	7.79				Y
19	7.68	60			Y
20	7.79				Y
21	7.74	80			Y
22	7.68				Y
23	7.70	80			Y
24	7.74				Y
25	7.98	100			Y
26	7.94				Y
27	7.74	80			Y
28	7.78				Y
29	7.54	60			Y
30	7.50				Y
31	7.46	60			Y

<<Have
minimums
been met
for this day?

County: Tillamook Agency: C

ENTRY POINT

A

PWS ID 4100367

HEBO JOINT WATER & SANITARY AUTH.

Sample period: October / 2022
Month/Year

Number of excursions* during this month: _____

(Over 9 excursions in 6 months is a violation. Entry
Point and Distribution excursions are cumulative)

Reference

Minimum Water Quality
Parameters as set by State:

pH 7.2

(No = N = Excursion) Total N's 0

Print Name: Justin Hartford

Signature: [Signature]

Date: _____

Send to OHD within 10 days after end of sampling period
Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381