

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	<>Have County: Tillamook Agency: C
1	7.81				4	minimums ENTRY POINT
2	7,74				11	been met
3	7-68					
ч	7.59	80				PWS ID 4100367
5	7.38					HEBO JOINT WATER & SANITARY AUTH
le	7.24					Sample period: April 12023 Month/Year
7	7.36					
8	7.46					
9	7,51					
10	7.36	60				
11	7.40					Number of excursions* during this month: Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative) Reference
15	7.20					
13	7.21					
14	7.26					
15	7.24			70°40°40°		
ما	7,24	80				
17	7.40					
18	7.36					
19	7.20					
20	7.21					
21	7,34					BALL SALL OF ITS
22	7.44	60				Minimum Water Quality Parameters as set by State: pH 7.2
23	7.39					
24	7.40					
25	7.46					
26	7.32					
27	7.30					
28	7.39	60				
29	7.45			6		Joshin Hartford
30	7.40				4	Print Name:
						Signature: 6/14/16
) = 1	= Exc	ursion) Total	N's	0	Date: 05/02/2023
1 1/	N - EXC	ursion	i) lota	N's	0	Send to OHD within 10 days of the and of any of

Send to OHD within 10 days after end of sampling period Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381