



Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.40				Y
2	7.35				
3	7.45				
4	7.56				
5	7.63				
6	7.71				
7	7.70				
8	7.72				
9	7.82				
10	7.99				
11	8.29				
12	8.79				
13	8.64				
14	8.60				
15	8.50				
16	8.33				
17	8.20				
18	8.36				
19	8.58				
20	8.58				
21	8.40				
22	8.22				
23	8.16				
24	7.80				
25	7.50				
26	7.46				
27	7.38				
28	7.35				
29	7.40				
30	7.42				
31	7.36				Y

<<Have
minimums
been met
for this day?

County Tillamook Agency: C

ENTRY POINT

A

PWS ID 4100367

HEBO JOINT WATER & SANITARY AUTH.

Sample period: Jan 1 2024

Month/Year

Number of excursions* during this month: ①

(Over 9 excursions in 6 months is a violation. Entry
Point and Distribution excursions are cumulative)

Reference

Minimum Water Quality
Parameters as set by State:

pH 7.2

Print Name: Justin Hartford

Signature: [Signature]

Date: 02/15/2024

(No = N = Excursion) Total N's 0

Send to OHD within 10 days after end of sampling period
Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381