

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.27	74			4
2	7.20				1
3	7.33				
4	7.33				
5	7.25				
6	7.37	3-57-52			
7	7.41				
8	7.39	76			
9	7.40				
10	7.47		3,71,880,3019		
11	7.44				
12	7.56	170		10	
13	7.58				
14	7.59				
15	7.66				
16	7.57				
17	7.49				
18	7,50	75			
19	7.48				
20	7.44				
21	7.47				
22	7.47				
23	7.51				
24	7.58	73			
25	7.49				
26	7,54				
27	7,60				
28	7.69				
29	7.59				
30	7.46				Ţ
31	7.30	٦١			4
No = 1	1 = Exc	cursion	) Tota	l N's	0

< <have minimums<="" th=""><th>County: Tillamook Agency: TILLAMOOK COUNTY  ENTRY POINT</th></have>	County: Tillamook Agency: TILLAMOOK COUNTY  ENTRY POINT
been met for this day?	EP-A
	PWS ID 4100367
НЕВО ЈО	OINT WATER & SANITARY AUTH
Sample pe	eriod: MAY, 2025

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk 60.0 (Alkalinity)
Print Name: Justin Hartford
Signature: 1 1 10 2025 503-392-6000
Send to DWP within 10 days after end of
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Reference