



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.55				Y
2	7.44				
3	7.59				
4	7.69				
5	7.33				
6	7.58				
7	7.52				
8	7.58				
9	7.43				
10	7.77				
11	7.57				
12	7.66				
13	7.30				
14	7.26				
15	7.86				
16	7.60				
17	7.51				
18	7.50				
19	7.87				
20	7.54				
21	7.55				
22	7.58				
23	7.62				
24	7.57				
25	7.46				
26	7.49				
27	7.56				
28	7.47				
29	7.45				
30	7.50				
31	7.55				Y

<<Have minimums been met for this day?

County Tillamook Agency: C

ENTRY POINT

A

PWS ID 4100367

HEBO JOINT WATER & SANITARY AUTH.

Sample period: APR. 2021
Month/Year

Number of excursions* during this month: 0
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

Reference

Minimum Water Quality Parameters as set by State:

pH 7.2

Print Name: LOUVE MOELLER

Signature: [Handwritten Signature]

Date: 5/3/21

(No = N = Excursion) Total N's 0

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381