



Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.42				Y
2	7.40				
3	7.48				
4	7.39				
5	7.42				
6	7.41				
7	7.38				
8	7.37				
9	7.42				
10	7.40				
11	7.37				
12	7.34				
13	7.35				
14	7.31				
15	7.41				
16	7.34				
17	7.34				
18	7.37				
19	7.39				
20	7.37				
21	7.44				
22	7.37				
23	7.36				
24	7.34				
25	7.34				
26	7.42				
27	7.35				
28	7.40				
29	7.41				
30	7.40				
31	7.51				Y

<<Have minimums been met for this day?

County Tillamook Agency: C

ENTRY POINT

A

PWS ID 4100367

HEBO JOINT WATER & SANITARY AUTH.

Sample period: July / 2021
 Month/Year

Number of excursions* during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

Reference

Minimum Water Quality Parameters as set by State:

pH 7.2

Print Name: Lenny Moeller
 Signature: Lenny E Moeller
 Date: 8/3/21

(No = N = Excursion) Total N's 0

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381