## Water Quality Parameter Monitoring Form Oregon Health Authority Lead & Copper Rule Corrosion Control

Day	PH	Alk	Phos	Other	Y/N
1	7.8				Υ
2	PLANT	OFF			
3	7.8				Υ
4	7.8				Υ
5	7.8				Υ
6	7.8				Υ
7	8.0				Υ
8	7.8				Υ
9	PLANT	OFF			
10	7.8				Υ
11	7.8				Υ
12	7.8				Υ
13	7.8				Υ
14	7.9				Υ
15	7.7				Υ
16	PLANT	OFF			
17	7.8				Υ
18	7.7				Υ
19	7.7				Υ
20	7.7				Υ
21	7.7				Υ
22	7.7				Υ
23	PLANT	OFF			
24	7.7				Υ
25	7.7				Υ
26	7.8				Υ
27	7.7				Υ
28	7.8				Υ
Total N	N's				0

(No = N = Excursion)

< <have been<="" minimums="" th=""><th colspan="4">ENTRY POINT</th></have>	ENTRY POINT			
met for this day?	PWS ID:	41-00473		
System N	lame:	Lebanon		
Entry Point:		WTP-B		
Sample P	eriod:		<u>Feb-25</u>	
		Month/Year		

Number of excursions during this month_	0
(Count the number of days when any WQF	was less
than the minimum required)	

Number of excursions during this month 0
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only

## Minimum Water Quality Parameter(s) as set by State: MIN MAX PH 7.0 9.0 Alk PO4 (Alkalinity) (Orthpphosphate) Other (\_\_\_\_\_)

Print Name:	Tyson Keene	
Signature:	1	

Date: 3~7~2 Sent to DWP within 10 days after end of sampling period.

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (971)-673-0471 Website: www.dhs.state.or.us/publichealth/dwp/index.cfm