

Water Quality Parameter Monitoring Form
Oregon Health Authority
Lead & Copper Rule Corrosion Control

| Day | PH | Alk | Phos | Other | Y/N |
|--|-----------|-----|------|-------|----------|
| 1 | 7.8 | | | | Y |
| 2 | 7.7 | | | | Y |
| 3 | 7.6 | | | | Y |
| 4 | 7.9 | | | | Y |
| 5 | 7.6 | | | | Y |
| 6 | Plant Off | | | | |
| 7 | 7.7 | | | | Y |
| 8 | 7.9 | | | | Y |
| 9 | 7.9 | | | | Y |
| 10 | 7.9 | | | | Y |
| 11 | 8.1 | | | | Y |
| 12 | 7.9 | | | | Y |
| 13 | Plant Off | | | | |
| 14 | 8.0 | | | | Y |
| 15 | 7.7 | | | | Y |
| 16 | 7.7 | | | | Y |
| 17 | 7.8 | | | | Y |
| 18 | 8.0 | | | | Y |
| 19 | 7.7 | | | | Y |
| 20 | Plant Off | | | | |
| 21 | 7.8 | | | | Y |
| 22 | 7.8 | | | | Y |
| 23 | 7.9 | | | | Y |
| 24 | 7.8 | | | | Y |
| 25 | 8.0 | | | | Y |
| 26 | 7.8 | | | | Y |
| 27 | Plant Off | | | | |
| 28 | 7.8 | | | | Y |
| 29 | 7.8 | | | | Y |
| 30 | 7.8 | | | | Y |
| | | | | | N |
| Total N's (No = N = Excursion) | | | | | 0 |

<<Have
 minimums been
 met for this day?

ENTRY POINT

PWS ID: 41-00473

System Name: Lebanon WTP

Entry Point: WTP-B

Sample Period: Apr-25

Month/Year

Number of excursions during this month 0

(Count the number of days when any WQP was less
 than the minimum required)

Number of excursions during this month 0

(Over 9 excursions in 6 months is a violation. Entry Point
 and Distribution excursions are cumulative)

For OHA use only

Minimum Water Quality

Parameter(s) as set by State:

| | MIN | MAX | |
|-------|------------|------------|------------------|
| pH | 7.0 | 9.0 | |
| Alk | | | (Alkalinity) |
| PO4 | | | (Orthpphosphate) |
| Other | | | (_____) |

Print Name: Tyson Keene

Signature: 

Date: 5-6-25

Sent to DWP within 10 days after end of sampling period.

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
 Phone: (971)-673-0471 Website: www.dhs.state.or.us/publichealth/dwp/index.cfm