

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.86	62.4			y
2					(
2 3 4 5		***************************************		20	
4		Z.			
5					
6	200				
7		,			
8	7.53	64.8			4
9					
10					
11	- 500				
12					
13					
14					
15	7.33	63.2			4
16					·
17					
18					
19			2		
20					
21					
22					
23				_	
24					
25					
26					
27					
28					
29	7.48	67.	2		Y
30					
31					
(No =	N = Ex	cursio	n) Tot a	al N's	D

< <have< td=""><td>County: Tillamook Agency: TILLAMOOK COUNTY</td></have<>	County: Tillamook Agency: TILLAMOOK COUNTY				
minimums	ENTRY POINT				
been met for this day?	EP-A				
	PWS ID 4100506				
NEAL	HKAHNIE WATER DISTRICT				
Sample pe	eriod: July 12024				

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	num Water Quality neter(s) as set by State:
pH Alk	7.0 50.0 (Alkalinity)

Print Name: Suff of Morrill

Signature: Suff of Morrill

Date & Phone#: 7.31,24 (503) 804-4649

Send to DWP within 10 days after end of

sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/