

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

рН	Alk	Phos	Other	Y/N
			***************************************	
7.52	72.4			Y
				1
0				
7.50	72.8			Y
			************	1
7.44	72.0			У
				/
	anni de la companya d			
				,
7.47	72.4			Y
				1
1				
1				
	7.52	7.52 72.4	7.52 72.4	7.52 72.4

< <have< th=""><th>County: Tillamook Agency: TILLAMOOK COUNTY</th></have<>	County: Tillamook Agency: TILLAMOOK COUNTY
minimums	ENTRY POINT
been met for this day?	EP-A
	PWS ID 4100506
NEAI	HKAHNIE WATER DISTRICT
Sample pe	eriod: Of 12024
	Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	um Water Quality neter(s) as set by State:
pH Alk	7.0 50.0 <i>(Alkalinity)</i>
u	X.

Signature: Staff of Morrill

Signature: Staff of Morrill

Date & Phone#: 10.31.24 (503) Bod-4149

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/