

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4	7.33	69.2			Y
5					•
6					
7					
8					
9					
10					
11	7.53	67.2			4
12					/
13					
14					
15					
16					
17					
18	7.45	68.0	9		Y
19					
20					
21					
22					
23					
24					<i>6</i> 1
25	7.53	63.2			4
26					/
27	1				
28					
29					
30					
31				,	
No =	N = Ex	cursion	n) Tota	al N's	D

<<Have minimums been met for this day?

County: Tillamook Agency: TILLAMOOK COUNTY

## **ENTRY POINT**

EP-A

PWS ID 4100506

NEAHKAHNIE WATER DISTRICT

Sample period: \_\_\_

Month/Year

## Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference -						
Minimum Water Quality Parameter(s) as set by State:						
pH Alk	7.0 50.0	(Alkalinity)				
i						

Print Name: South Morrill
Signature: Sett Alleutt

Date & Phone#://-30-24 (503) 804-4649

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/