

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1		```			
2	7.44	600			4
2 3 4					
4					
5					
5 6 7					-
7					
8					
9	7.51	56.8			Y
10					
11					
12					
13					
14	***************************************				
15					
16	7:64	59.2			Y
17	and the second s				
18					
19					
20					
21					
22					
23	7.57	624			Y
24					
25					
26					
27					
28					
29					
30	7.32	56.8			1
31					1
No =	N = Ex	cursio	n) Tot a	al N's	A

< <have< td=""><td>County: Tillamook Agency: TILLAMOOK COUNTY</td></have<>	County: Tillamook Agency: TILLAMOOK COUNTY				
minimums	ENTRY POINT				
been met for this day?	EP-A				
	PWS ID 4100506				
NEAHKAHNIE WATER DISTRICT					
Sample pe	eriod: <u>Dec /2024</u> Month/Year				

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

-Reference						
Minimum Water Quality Parameter(s) as set by State:						
pH 7.0 Alk 50.0 (Alkalinity)						

Print Name: Suff a Marrill Signature: Just a Marrill Date & Phone#: 12-31-2021 503-904-4649

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/