

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5	7.52	64.8			Y
6					
7					
8					
9					
10					0
11					
	7.49	72.8			Y
13	and the second section of the second	dandri e ubilani, cinetaruli ciner spundatu			
14			-		
15					
16					
17					
18					
19	7.46	70.0			Y
20					
21					
22					
23					
24					
25					
26	7.44	704			Y
27					
28					
29					
30	1	-			
31		-			
	N = Ex	cursio	n) <b>Tot</b> a	al N's	Ø

< <have< td=""><td>County: Tillamook Agency: TILLAMOOK COUNTY</td></have<>	County: Tillamook Agency: TILLAMOOK COUNTY					
minimums	ENTRY POINT					
this day?	EP-A					
PWS ID 4100506						
NEAHKAHNIE WATER DISTRICT						
Sample period: May ZoZ5 Month/Year						
NEAL	PWS ID 4100506 HKAHNIE WATER DISTRICT					

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

/\energineering	
Minimum Water Quality Parameter(s) as set by State:	
pH 7.0 Alk 50.0 (Alkalinity)	
Print Name: Jesemy Rex Signature: Jewy Rex	
Date & Phone#:5/31/25 (206) 919-429	_
Send to DWP within 10 days after end of sampling period	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

-Poforonce -