

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	2				
2					
3 4	7.58	58.8			Y
4					
5					
6					
7					
8					
9					
10	7.82	62.4			Y
11					
12	185				
13					
14					
15					
16					
17	7.82	Col.6			×
18					
19					
20					
21					
22					
23					
24	7.43	624			Y
25					
26					
27					
28					
29					
30		9			
31				20	
No = N = Excursion) Total N's					Ø

<<Have minimums been met for this day?

County: Tillamook Agency: TILLAMOOK COUNTY

FNTRY POINT

ENTRY POINT EP-B

PWS ID 4100506

NEAHKAHNIE WATER DISTRICT

Sample period: FEB. ZOZ5

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by State:				
pH 7.0 Alk 50.0 (Alkalinity)				
Print Name: Phi Chick Signature: Phil Chick				

Send to DWP within 10 days after end of sampling period

Date & Phone#: 2-28-25

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Reference