

## vvaler Quality Farameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Clackamas Agency: C</th></have<>	County: Clackamas Agency: C
OA!	7.882		13		4	minimums	ENTRY POINT
18	785		13		4	been met for this day?	A
	-						PWS ID 4100547
						MULINO WATER DISTRICT	
						Sample	period: 09/2024 Month/Year
						Number of	excursions during this month:
						Point and D An 'excursion	cursions in 6 months is a violation. Entry Distribution excursions are cumulative). On' is any day in which the water quality os) fall below the minimum set by the
						Refe	erence
							Minimum Water Quality Parameter(s) as set by State:
						pH 7.3	
						D.:1 Al-:-	and Marinel Traca
-						Print Nan	
No = 1	N = Ex	cursion	n) <b>Tot</b> a	al N's	A	Signature Date: <u>09/</u>	18/2021 /10/ M
			,				nin 10 days after end of sampling period

Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp