

water Quality Farameter Monitoring Form

Lead & Copper Rule Corrosion Control

Оау	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Clackamas Agency: C</th></have<>	County: Clackamas Agency: C	
08	7.84		13		4	minimums been met for this day?	ENTRY POINT	
22	7,82		1.3		4		A	
	-						PWS ID 4100547	
						MULINO WATER DISTRICT		
						Sample	period: 01/2035 Month/Year	
						Number of	excursions during this month:	
						Point and L An 'excursi	cursions in 6 months is a violation. Entry Distribution excursions are cumulative). Fon' is any day in which the water quality (s) fall below the minimum set by the	
						-Reference Minimum Water Quality Parameter(s) as set by State:		
						Print Na Signatur	me: MARIN TROGODN Te: Mam Mayby	
 No =	: N = E	xcursio	on) Tot	al N'	s E		129/2025	
							thin 10 days after end of sampling period	

Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp